



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Gadwall Drive East

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 718 L.F. of drainage system. Cleaned out 718 L.F. of roadside ditch.

**Duration:** 3/2/16 - 3/16/16

2016-600 / Gadwall Drive East	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
HAUL / Hauling	19.0	\$423.13	\$151.81	\$46.06	\$0.00	\$273.98	\$894.98
ONJV / Onsite Job Visit	8.0	\$284.86	\$28.40	\$12.78	\$0.00	\$205.25	\$531.29
PI / Project Inspection	1.0	\$45.60	\$3.62	\$1.42	\$0.00	\$33.96	\$84.60
PL / Project Layout	2.0	\$91.20	\$7.24	\$2.84	\$0.00	\$67.92	\$169.20
RSDCL / Roadside Ditch - Cleanout	80.0	\$1,690.30	\$314.08	\$37.19	\$0.00	\$1,066.00	\$3,107.57
SG / Shoot Grade	15.0	\$348.75	\$17.70	\$6.04	\$0.00	\$215.70	\$588.19
UTLOC / Utility locates	0.5	\$12.35	\$0.00	\$0.00	\$0.00	\$6.62	\$18.97
<b>2016-600 / Gadwall Drive East Sub Total</b>	<b>126.0</b>	<b>\$2,907.94</b>	<b>\$522.85</b>	<b>\$106.33</b>	<b>\$0.00</b>	<b>\$1,876.04</b>	<b>\$5,413.15</b>
 <b>Grand Total</b>	 <b>126.0</b>	 <b>\$2,907.94</b>	 <b>\$522.85</b>	 <b>\$106.33</b>	 <b>\$0.00</b>	 <b>\$1,876.04</b>	 <b>\$5,413.15</b>

Before



After





Project: Gadwall Drive East

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2016-600

Township/SW Dist:  
Ladys Island/7

Completed:  
March 2016



### Legend

#### Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 40 80 160 240 320  
Feet

1 inch = 170 feet

Prepared By: BC Stormwater Management Utility

Date Print: 03/12/2016

File: C:\project summaries map\Gadwall Drive East\_2016-600