



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Bonaire Circle South

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 60 L.F. of drainage system. Removed blockage from flowline.  
Cleaned out 60 L.F. of roadside ditch.

**Duration:** 7/12/16

<b>2017-504 / Bonaire Circle South</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
RSDCL / Roadside Ditch - Cleanout	16.0	\$361.28	\$71.13	\$31.92	\$0.00	\$217.12	\$681.45
<b>2017-504 / Bonaire Circle South</b>	<b>16.5</b>	<b>\$373.02</b>	<b>\$71.13</b>	<b>\$31.92</b>	<b>\$0.00</b>	<b>\$223.74</b>	<b>\$699.81</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>16.5</b>	<b>\$373.02</b>	<b>\$71.13</b>	<b>\$31.92</b>	<b>\$0.00</b>	<b>\$223.74</b>	<b>\$699.81</b>

Before



After





Project: Bonaire Circle South

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2017-504

Township/SW Dist:  
Port Royal Island/6

Completed:  
July 2016

### Legend

#### Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 50 100 200 300 400  
Feet

1 inch = 210 feet

Prepared By: BC Stormwater Management Utility

Date Print:08/31/16

File:C:\project summaries map/Bonaire Circle\_2017-504