

## Beaufort County Public Works Stormwater Infrastructure

## otorniwater inirastri

Project Summary

Project Summary: Katie Miller Drive and Ceasar Place

**Activity:** Routine/Preventive Maintenance

## **Narrative Description of Project:**

**Duration:** 2/10/16 - 2/23/16

Project improved 3,249 L.F. of drainage system. Cleaned out 2,971 L.F. of roadside ditch and (2) catch basins. Jetted (4) driveway pipes, (1) crossline pipe and 278 L.F. of roadside pipe. Hydroseeded for erosion control.

2016-584 / Katie Miller Dr/Ceasar Place	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
CBCO / Catch basin - clean out	20.0	\$457.60	\$86.80	\$41.79	\$0.00	\$297.00	\$883.19
CCO / Channel - cleaned out	90.0	\$1,888.95	\$344.49	\$34.65	\$0.00	\$1,188.10	\$3,456.19
HAUL / Hauling	60.0	\$1,336.20	\$479.40	\$162.15	\$0.00	\$865.20	\$2,842.95
HYDR / Hydroseeding	20.0	\$415.30	\$42.58	\$82.20	\$0.00	\$260.35	\$800.43
ONJV / Onsite Job Visit	8.0	\$273.44	\$28.32	\$16.32	\$0.00	\$195.76	\$513.84
PROFS / Professional Services	0.0	\$0.00	\$0.00	\$0.00	\$224.15	\$0.00	\$224.15
RSDCL / Roadside Ditch - Cleanout	190.0	\$3,976.50	\$780.21	\$85.09	\$0.00	\$2,498.30	\$7,340.10
RSPJ / Roadside Pipe - Jetted	8.0	\$178.24	\$34.72	\$23.01	\$0.00	\$114.72	\$350.69
2016-584 / Katie Miller Dr/Ceasar Place	396.5	\$8,537.98	\$1,796.52	\$445.21	\$224.15	\$5,426.04	\$16,429.90
Sub Total							
Grand Total	396.5	\$8,537.98	\$1,796.52	\$445.21	\$224.15	\$5,426.04	\$16,429.90











