



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Irongate Subdivision - Rework

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 345 L.F. of drainage system. Reconstructed 345 L.F. of channel. Reinstalled (1) access pipe to correct elevation. Installed strawmat and hydroseeded for erosion control.

Completion: Nov-15

2015-020B / Irongate Subdivision	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
CREC / Channel - reconstructed	15.0	\$359.75	\$136.98	\$28.23	\$0.00	\$226.75	\$751.71
HAUL / Hauling	17.0	\$378.59	\$135.83	\$81.60	\$0.00	\$245.14	\$841.16
HYDR / Hydroseeding	9.0	\$215.85	\$10.62	\$127.05	\$0.00	\$136.05	\$489.57
ONJV / Onsite Job Visit	17.0	\$648.41	\$60.82	\$30.71	\$0.00	\$448.23	\$1,188.17
PI / Project Inspection	3.0	\$136.80	\$10.86	\$5.10	\$0.00	\$101.88	\$254.64
PL / Project Layout	20.0	\$465.05	\$17.70	\$3.62	\$0.00	\$292.90	\$779.27
WSDR / Workshelf - Dressed	28.0	\$651.07	\$67.18	\$56.15	\$0.00	\$410.06	\$1,184.46
2015-020B / Irongate Subdivision Sub Total	109.5	\$2,867.27	\$439.99	\$332.46	\$0.00	\$1,867.62	\$5,507.34
 Grand Total	 109.5	 \$2,867.27	 \$439.99	 \$332.46	 \$0.00	 \$1,867.62	 \$5,507.34

Before



During



After





Project: Irongate Subdivision

Activity: Routine/ Preventive Maintenance

Project #: 2016-020B

Township: Port Royal Island

Completed: November 2015

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 15 30 60 90 120 Feet

1 inch = 67 feet

Prepared By: BC Stormwater Management Utility

Date Print: 11/23/2015

File: C:\project summaries map\Irongate Subdivision_2016-020B