



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Pinewood Circle Subdivision

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

**Duration:** 8/4/16 - 8/29/16

Project improved 3,909 L.F. of drainage system. Cleaned out 3,909 L.F. of roadside ditch. Jetted (50) driveway pipes. Hydroseeded for erosion control.

<b>2017-513 / Pinewood Circle Subdivision</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
DPJT / Driveway Pipe - Jetted	46.0	\$1,057.68	\$199.64	\$144.68	\$0.00	\$684.24	\$2,086.24
HAUL / Hauling	49.0	\$1,091.23	\$461.58	\$105.12	\$0.00	\$706.58	\$2,364.51
RSDCL / Roadside Ditch - Cleanout	225.0	\$4,979.90	\$909.67	\$596.22	\$0.00	\$3,158.10	\$9,643.89
UTLOC / Utility locates	0.5	\$12.35	\$0.00	\$0.00	\$0.00	\$6.62	\$18.97
<b>2017-513 / Pinewood Circle Subdivision Sub Total</b>	<b>321.0</b>	<b>\$7,152.91</b>	<b>\$1,570.89</b>	<b>\$846.02</b>	<b>\$0.00</b>	<b>\$4,562.15</b>	<b>\$14,131.96</b>
 <b>Grand Total</b>	 <b>321.0</b>	 <b>\$7,152.91</b>	 <b>\$1,570.89</b>	 <b>\$846.02</b>	 <b>\$0.00</b>	 <b>\$4,562.15</b>	 <b>\$14,131.96</b>

Before



During



After







Project: Pinewood Circle

Activity: Routine/ Preventive Maintenance

Project #: 2017-513

Township/SW Dist: Port Royal Island/6

Completed: August 2016

### Legend

#### Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 100 200 400 600 800 Feet

1 inch = 420 feet

Prepared By: BC Stormwater Management Utility

Date Print: 09/28/16

File: C:\project summaries map\Pinewood Circle\_2017-513