

Project Summary: Peaches Hill Circle and Scott Hill Road

Activity: Routine/Preventive Maintenance

Duration: 06/07/2022 - 06/28/2022

Narrative Description of Project:

Project improved 6,110 L.F. of drainage system. Cleaned out 3,188 L.F. of roadside ditch and 2,922 channel ditch.


2022-566 / Peaches Hill Circle and Scott Hill	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
Drive	Hours	Cost	Cost	Cost	Cost	Cost	Cost
AUDIT / Audit Project	2.00	\$65.48	\$0.00	\$0.00	\$0.00	\$40.42	\$105.90
CCO / Channel - cleaned out	184.00	\$5,404.36	\$871.27	\$540.24	\$0.00	\$3,336.00	\$10,151.87
HAUL / Hauling	128.00	\$3,562.00	\$2,287.20	\$943.91	\$0.00	\$2,198.48	\$8,991.59
HEQ / Haul equipment	16.00	\$530.40	\$304.96	\$117.30	\$0.00	\$327.36	\$1,280.02
ONJV / Onsite Job Visit	4.00	\$166.88	\$17.40	\$20.60	\$0.00	\$0.00	\$204.88
RSDCL / Roadside Ditch - Cleanout	120.00	\$3,559.36	\$656.01	\$362.50	\$0.00	\$2,197.04	\$6,774.91
Grand Total	454.00	\$13,288.48	\$4,136.84	\$1,984.55	\$0.00	\$8,099.30	\$27,509.17

Before During After

(No Picture Available)








1 inch = 670 feet

Date Print: 11/22/22

File:C:\project summaries map/Peaches Hill And Scott Hill Channel Map 1_2-22-566




Project: Peaches Hill Circle & Scott Hill Road Map #2

Activity: Routine/
Preventive
Maintenance


Project #: 2022-566

Township/SW Dist: St Helena Island/8

Completed: June 2022



Prepared By: BC Stormwater Management Utility Date Print:11/22/22



0 70140 280 420 560 Feet

1 inch = 420 feet

Prepared By: BC Stormwater Management Utility Date Print:11/22/22

File:C:\project summaries map/Peaches Hill And Scott Hill Channel Map 3_2-22-566