



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Jasmine Hall Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 800 L.F. of drainage system. Cleaned out 800 L.F. of roadside ditch.

Duration: 2/9/16

2016-593 / Jasmine Hall Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
HAUL / Hauling	8.0	\$178.16	\$63.92	\$14.81	\$0.00	\$115.36	\$372.25
ONJV / Onsite Job Visit	4.0	\$136.72	\$14.16	\$8.16	\$0.00	\$97.88	\$256.92
RSDCL / Roadside Ditch - Cleanout	32.0	\$664.48	\$89.14	\$18.13	\$0.00	\$416.56	\$1,188.31
2016-593 / Jasmine Hall Road Sub Total	44.5	\$991.11	\$167.22	\$41.10	\$0.00	\$636.42	\$1,835.84
Grand Total	44.5	\$991.11	\$167.22	\$41.10	\$0.00	\$636.42	\$1,835.84

Before



During



After





Project: Jasmine Hall Road

Activity: Routine/ Preventive Maintenance














Project #: 2016-593

Township/SW Dist: Sheldon/5

Completed: February 2016

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 50 100 200 300 400 Feet

1 inch = 210 feet

Prepared By: BC Stormwater Management Utility

Date Print:07/20/16

File:C:\project summaries map\Jasmine Hall Road_2016-593