



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Cee Cee Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 5,210 L.F. of drainage system. Removed blockages and check dams from 5,210 L.F. of roadside ditch. Jetted (3) crossline pipes and (12) driveway pipes.

Completion: Nov-15

2016-568 / Cee Cee Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	5.0	\$117.45	\$0.00	\$0.00	\$0.00	\$66.15	\$183.60
HAUL / Hauling	18.0	\$415.56	\$95.88	\$37.11	\$0.00	\$271.86	\$820.40
ONJV / Onsite Job Visit	6.0	\$187.93	\$21.24	\$8.50	\$0.00	\$115.62	\$333.29
PRRECON / Project Reconnaissance	2.0	\$91.20	\$7.24	\$5.10	\$0.00	\$67.92	\$171.46
RB / Remove blockage from flowline	18.0	\$395.28	\$71.13	\$16.29	\$0.00	\$252.72	\$735.42
2016-568 / Cee Cee Road Sub Total	49.0	\$1,207.42	\$195.49	\$67.00	\$0.00	\$774.27	\$2,244.17
 Grand Total	 49.0	 \$1,207.42	 \$195.49	 \$67.00	 \$0.00	 \$774.27	 \$2,244.17

Before



During



After




Project: Cee Cee Road

Activity: Routine/
Preventive
Maintenance

Project #:
2016-568

Township:
St Helena Island

Completed:
November 2015



Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 87.5175 350 525 700
Feet

1 inch = 360 feet

Prepared By: BC Stormwater Management Utility

Date Print: 11/30/2015

File: C:\project summaries map\CeeCee Road_2016-568