



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Sheldon Tree Removal - Mount Pisgah Church Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Removed fallen tree from workshelf.

Completion: Oct-15

2016-504 / Sheldon Tree Removal	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
HAUL / Hauling	8.0	\$178.16	\$63.92	\$114.65	\$0.00	\$115.36	\$472.09
ONJV / Onsite Job Visit	2.0	\$61.50	\$7.08	\$1.72	\$0.00	\$36.46	\$106.76
RMTRW / Remove trees - Workshelf	20.0	\$463.06	\$61.58	\$18.01	\$0.00	\$292.20	\$834.85
2016-504 / Sheldon Tree Removal Sub Total	30.5	\$714.47	\$132.58	\$134.38	\$0.00	\$450.64	\$1,432.06
 Grand Total	 30.5	 \$714.47	 \$132.58	 \$134.38	 \$0.00	 \$450.64	 \$1,432.06

Before



During



After





Project: Sheldon
Tree Removal-
Mount Pisgah
Church Road

Activity: Routine/
Preventive
Maintenance

Project #:
2016-504

Township:
Sheldon

Completed:
October 2015

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 15 30 60 90 120
Feet

1 inch = 67 feet

Prepared By: BC Stormwater Management Utility

Date Print:10/14/2015

File:C:\project summaries map/Sheldon Tree Removal-Mount Pisgah Church Road_2016-504