



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Riley Road Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Duration: 9/1/2015 - 9/2/2015

Project improved 300 L.F. of drainage system. Cleaned out 300 L.F. of channel.

| 2016-531 / Riley Road Channel #1 | Labor Hours | Labor Cost | Equipment Cost | Material Cost | Contractor Cost | Indirect Labor | Total Cost |
|---|------------------------|-----------------------|---------------------------|--------------------------|----------------------------|---------------------------|-------------------|
| AUDIT / Audit Project | 0.5 | \$11.75 | \$0.00 | \$0.00 | \$0.00 | \$6.62 | \$18.36 |
| CCO / Channel - cleaned out | 8.0 | \$184.08 | \$30.79 | \$17.70 | \$0.00 | \$119.64 | \$352.21 |
| HAUL / Hauling | 2.5 | \$55.68 | \$15.53 | \$24.78 | \$0.00 | \$36.05 | \$132.03 |
| ONJV / Onsite Job Visit | 2.0 | \$61.50 | \$7.08 | \$6.80 | \$0.00 | \$36.46 | \$111.84 |
| 2016-531 / Riley Road Channel #1 Sub Total | 13.0 | \$313.00 | \$53.40 | \$49.28 | \$0.00 | \$198.77 | \$614.44 |
| | | | | | | | |
| Grand Total | 13.0 | \$313.00 | \$53.40 | \$49.28 | \$0.00 | \$198.77 | \$614.44 |

(Pictures Not Available)



Project: Riley Road
Channel #1

Activity: Routine/
Preventive
Maintenance

Project #:
2016-531

Township/SW Dist:
Port Royal Island/
2&6

Completed:
September 2015

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 40 80 160 240 320
Feet

1 inch = 170 feet

Prepared By: BC Stormwater Management Utility

Date Print:05/25/16

File:C:\project summaries map\Riley Road Channel #1_2016-531