



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Albertha Fields Circle

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Removed blockage from flowline.

**Duration:** 4/7/16

**2016-615 / Albertha Fields Circle**

	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
HAUL / Hauling	4.0	\$89.08	\$31.96	\$9.06	\$0.00	\$57.68	\$187.78
ONJV / Onsite Job Visit	2.0	\$61.50	\$7.08	\$1.42	\$0.00	\$36.46	\$106.46
RB / Remove blockage from flowline	10.0	\$231.54	\$46.84	\$6.80	\$0.00	\$146.10	\$431.28
<b>2016-615 / Albertha Fields Circle</b>	<b>16.5</b>	<b>\$393.87</b>	<b>\$85.88</b>	<b>\$17.28</b>	<b>\$0.00</b>	<b>\$246.86</b>	<b>\$743.88</b>
<b>Sub Total</b>							

<b>Grand Total</b>	<b>16.5</b>	<b>\$393.87</b>	<b>\$85.88</b>	<b>\$17.28</b>	<b>\$0.00</b>	<b>\$246.86</b>	<b>\$743.88</b>
--------------------	-------------	-----------------	----------------	----------------	---------------	-----------------	-----------------

Before



During



After







Project: Albertha  
Fields Circle

Activity: Routine/  
Preventive  
Maintenance














Project #:  
2016-615

Township/SW Dist:  
Sheldon/5

Completed:  
April 2016

### Legend

#### Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 37.575 150 225 300  
Feet

1 inch = 170 feet

Prepared By: BC Stormwater Management Utility  
Date Print: 05/12/16  
File: C:\project summaries map\Albertha Fields Circle\_2016-615