

Project Summary: Westwood Circle

Activity: Routine/Preventive Maintenance

Duration: 01/31/2023 - 04/18/2023

Narrative Description of Project:

Project improved 2,874 L.F. of drainage system. Cleaned out 1,646 L.F. of roadside ditch and 1,204 L.F. of valley drain. Jetted (15) driveway pipes, (3) crossline pipes and 24 L.F. of roadside pipe.


2023-586 / Westwood Circle	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Cost	Cost
AUDIT / Audit Project	1.50	\$49.11	\$0.00	\$0.00	\$0.00	\$30.32	\$79.43
COVD / Cleaned Out Valley Drains	72.00	\$1,783.26	\$370.56	\$89.50	\$0.00	\$779.04	\$3,022.36
DPJT / Driveway Pipe - Jetted	16.00	\$503.37	\$306.56	\$103.72	\$0.00	\$310.72	\$1,224.37
HAUL / Hauling	40.00	\$1,203.76	\$762.40	\$315.00	\$0.00	\$151.04	\$2,432.20
ONJV / Onsite Job Visit	30.00	\$1,251.60	\$130.50	\$37.80	\$0.00	\$0.00	\$1,419.90
RSDCL / Roadside Ditch - Cleanout	120.00	\$2,935.53	\$555.84	\$139.90	\$0.00	\$1,168.56	\$4,799.83
UTLOC / Utility locates	1.00	\$41.72	\$4.35	\$6.47	\$0.00	\$0.00	\$52.54
Grand Total	280.50	\$7,768.34	\$2,130.21	\$692.39	\$0.00	\$2,439.68	\$13,030.62

Before During After









1 inch = 170 feet

Date Print:04/11/23

File:C:\esproject summaries map/Westwood Circle Map #1_2023-586



Feet

1 inch = 83 feet Date Print:04/11/23 File:C:\esproject summaries map/Westwood Circle Map #2_2023-586