



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: St. Helena Island Washout Repair - Sea Island Parkway

Activity: Routine/Preventive Maintenance

Duration: 07/26/2022

Narrative Description of Project:

Repaired a washout.

| 2023-541 / St. Helena Island Washout Repair | Labor Hours | Labor Cost | Equipment Cost | Material Cost | Contractor Cost | Indirect Cost | Total Cost |
|----------------------------------------------------|--------------------|-------------------|-----------------------|----------------------|------------------------|----------------------|-------------------|
| AUDIT / Audit Project | 0.50 | \$20.81 | \$0.00 | \$0.00 | \$0.00 | \$10.41 | \$31.22 |
| RPWO / Repaired Washout | 12.00 | \$379.04 | \$106.59 | \$145.12 | \$0.00 | \$233.96 | \$864.71 |
| Grand Total | 12.50 | \$399.85 | \$106.59 | \$145.12 | \$0.00 | \$244.37 | \$895.93 |

(No Pictures Available)



Project: St. Helena Island Washout / Sinkhole Repair- Sea Island Parkway














Activity: Routine/ Preventive Maintenance

Project #: 2023-423

Township/SW Dist: St. Helena Island/8

Completed: July 2022

Legend

- Drainage Type**
-  Access Pipe
 -  Bleeder Pipe
 -  Channel Pipe
 -  Channel
 -  Stream
 -  Crossline Pipe
 -  Driveway Pipe
 -  Lateral
 -  Lateral Pipe
 -  River
 -  Road Pipe
 -  Roadside
 -  Roadside Pipe

0 50 100 200 300 400 Feet

1 inch = 270 feet

Prepared By: BC Stormwater Management Utility

Date Print: 07/31/23

File: C:\project summaries map\SHI Washout/Sinkhole Repair- Sea Island Parkway_2023-423